

## **Gas Refrigerator Troubleshooting and Diagnostics**

### Problem

Refrigerator will not cool after initial installation or after moving it to a new location.

### Discussion

Check the tube at the back of the unit to see if it is frosting. If this is the case, the unit likely has formed a bubble. The bubble will eventually resolve on its own, but you can also fix this by tipping the refrigerator forward on the doors or on its side by the chimney. This will eliminate the bubble, and the refrigerator can then be placed upright and relit.

### Note

When moving a refrigerator, try to transport it upright or flat on its chimney side to prevent bubble formation.

Courtesy of Clarence Imhoff, Hardware Service Tech